





HIETAKARI®




8/25 0URLM


501



Parts




1. x4




4/83 14RLM

2. 5x25 mm
x7




4/83 31RLM

3. 3.5x39 mm
x7




8/85 51RLM

4. x5




5. x1


Tools




A




Ø4 mm
Ø5 mm
B




C – Silicone
D – Glue






E




F




1




II.










III.







IV.



2



3



4

